

12/24/96





FIG. 1

62226 U.S. PTO

08/773677

12/24/86

12/24/96



X-RAY DIFFRACTION ANGLE, DEGREE

FIG. 2




FIG. 3

12/24/96
08/773677
6226 U.S. PTO




FIG. 4

12/24/96
08/773677
6226 U.S. PTO




FIG. 5

12/24/96

08/773677
62226 U.S. PTO

X-RAY DIFFRACTION ANGLE, DEGREE




FIG. 6

12/24/96
08/773677
62226 U.S. PTO




FIG. 7

12/24/96

08/11/96
6226 U.S. PTO
6226 U.S. PTO

12/24/96




FIG. 8

- * CONTAMINATED FEED INCLUDES CONTAMINATED SEDIMENTS AND SOILS
- ** CORRECTIVE COMPONENT INCLUDES ALUMINA/BAUXITE/FERRIC OXDE/FLUXING AGENT

12/24/96



VENT
EXHAUST




FIG. 9

- * CONTAMINATED FEED INCLUDES CONTAMINATED SEDIMENTS AND SOILS
- ** CORRECTIVE COMPONENT INCLUDES ALUMINA/BAUXITE/FERRIC OXDE/FLUXING AGENT




FIG. 10

- * CONTAMINATED FEED INCLUDES CONTAMINATED SEDIMENTS AND SOILS
- ** CORRECTIVE COMPONENT INCLUDES ALUMINA/BAUXITE/FERRIC OXDE/FLUXING AGENT